Oil Field Environmental Incident Summary

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: 5393 3-10 CTB

Field Name: SANISH Well File #: 0

Date Incident:11/13/2013Time Incident:0400Facility ID Number:217618-01County:MOUNTRAILTwp:153Rng:93Sec:3Qtr:LO T4

Location Description:

Submitted By: Jared Iverson Received By:

Contact Person: Jared Iverson

1001 FANNIN STE 1500 HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	10	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Followup Units

Potential Environmental Impacts:

Impact to soil on location.

Action Taken or Planned:

Wells were turned out of Production treater. Clean up crew will be dispatched to clean up spill.

Wastes Disposal Location: Clean Harbors.

Agencies Involved:

Updates

Date: 12/13/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to treater popoff, remained on location, according to the report. NDIC retains oversight.